



Metal Age

Care & Maintenance

Winfield Design

400 High Grove Blvd
Glendale Heights, IL 60139
tel 800.486.6800
fax. 800.430.6807

www.winfielddesign.com

Remove surface dirt and soiling conditions, using a soft clean sponge and warm water. Rinse with clear, clean water. If conditions persist, use a mild liquid detergent and rinse with clean water. Gently pat dry with a soft towel, or clean tissue. Avoid hard rubbing, and the use of too much water, as excessive water or soaking may damage the material.