



400 High Grove Blvd  
Glendale Heights, IL 60139  
Telephone: 1-800-486-6800  
Fax: 1-800-430-6807

## **Natural Textiles**

### **Care and Maintenance Instructions**

#### **Maintenance**

Periodic vacuuming is recommended to prevent airborne dust from building up on the wallcovering surface. The frequency of vacuuming should be increased in particularly polluted environments.

#### **Cleaning**

All Natural Textile wallcoverings are finished with a stain resistant topcoat to provide increased protection against staining from most water and oil agents.

When splashed, the contaminant will form beads on the surface of the wall covering, and, in most cases these can be removed by gentle blotting with a clean absorbent tissue. Remove any such splashes when still wet, but do not rub as you may push them into the wall material and create a stain.

The stain should be attended to immediately; once stains are dried in, it is very difficult to remove them. Stains should be cleaned by gentle rubbing with a clean lightly dampened sponge. For more stubborn stains a neutral detergent solution may be used. Always work from the outside in towards the center of the stain.

If further steps are required contact Winfield Thybony Design customer service at 800-486-6800.

**Natural Textiles is Marketed Nationally by Kravet Inc.**